2009 Structure Summary Report

Overall Unit and Item Ratings

Butte County Public Works

Big Chico Creek Diversion Structure

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	М
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Sluice/Slide Gates	Α
	Manual Gate Operators	Α
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Closure Structures	Α
	Monolith Joints	Α

Lindo Channel Control Structure

Overall Unit Rating	Rated Item	Item Rating
Α	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	Α
	Culverts: Inlets / Outlets	Α
Culverts: Breaks / Holes /		Α
	Sluice/Slide Gates	Α
	Manual Gate Operators	Α
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	М
	Concrete Foundations	Α
Security Fencing		Α
	Closure Structures	Α
	Monolith Joints	Α

Lindo Channel Diversion Weir

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	Α
	Shoaling / Sedimentation	Α
	Erosion / Bank Caving	Α
	Revetments	Α
	Encroachments	М
	Concrete Surfaces	Α
	Concrete Tilting / Settlement	Α
	Concrete Foundations	Α
	Security Fencing	Α
	Monolith Joints	Α

Flood Control Project Maintenance

Unit Cover Sheet

2009 Structure Inspection Results

Structure
Big Chico Creek Diversion Structure

Structure Rating	A
Date of Inspection	8/12/2009
DWR Inspector	Bob Duffey
Accompanied By	

Levee Inspection Report By Mile - Structure 2009

Butte County Public Works

Structure	Structure Length	Inspection Start/End	Inspector
Big Chico Creek Diversion Structure		08/12/2009 08/12/2009	Bob Duffey

LMR	Levee	Mile	Catagony	Item	Rating ** Location	Action/Comment	GPS Latitu	ide/Long	itude	Issue No.
No.	Start	End	Category	item	tion	Action/Comment	Start	En	d E	No.
1	0.00	0.00	Structures	Vegetation & Obstructions	Α			0	0	Y 1
2	0.00	0.00	Structures	Shoaling / Sedimentation	M			0	0	2
3	0.00	0.00	Structures	Erosion / Bank Caving	Α			0	0	3
4	0.00	0.00	Structures	Revetments	Α			0	0	4
5	0.00	0.00	Structures	Encroachments	Α			0	0	5
6	0.00	0.00	Structures	Culverts: Inlets / Outlets	N			0	0	6
7	0.00	0.00	Structures	Culverts: Breaks / Holes / Cracks	N			0	0	7
8	0.00	0.00	Structures	Metal Pipes	N			0	0	8
9	0.00	0.00	Structures	Trash Racks	N			0	0	9
10	0.00	0.00	Structures	Flap Gates	N			0	0	10
11	0.00	0.00	Structures	Sluice/Slide Gates	Α			0	0	11
12	0.00	0.00	Structures	Electric Gate Operators	N			0	0	12
13	0.00	0.00	Structures	Manual Gate Operators	Α			0	0	13
14	0.00	0.00	Structures	Concrete Surfaces	А			0	0	14
15	0.00	0.00	Structures	Concrete Tilting / Settlement	Α			0	0	15
16	0.00	0.00	Structures	Concrete Foundations	Α			0	0	16
17	0.00	0.00	Structures	Security Fencing	N			0	0	17

* Location LS : Land Side WS : Water Side CR : Crown ** Rating

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

Levee Inspection Report By Mile - Structure 2009

Butte County Public Works

Structure	Structure Length	Inspection Start/End	Inspector
Big Chico Creek Diversion Structure		08/12/2009 08/12/2009	Bob Duffey

LMR	Levee	Mile	Catamani	lta ma	Rating ** Location	A skin y / Common and	GPS Latitude	e/Longitude	Issue No.
No.	Start	End	Category	Item	ing * ation	Action/Comment	Start	End	oto No.
18	0.00	0.00	Structures	Closure Structures	Α		0	0	18
19	0.00	0.00	Structures	Trash Rakes	N		0	0	19
20	0.00	0.00	Structures	Other Metallic Items	N		0	0	20
21	0.00	0.00	Structures	Monolith Joints	Α		0	0	21
22	0.00	0.00	Structures	Safety	N		0	0	22

** Rating

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

Levee Inspection Report By Mile - Structure 2009

Butte County Public Works

Structure	Structure Length	Inspection Start/End	Inspector
Big Chico Creek Diversion Structure		08/12/2009 08/12/2009	Bob Duffey

Levee Mile Report Line	1				
Start Levee Mile	0.00				
End Levee Mile	0.00				
Location					
Category	Structures				
Item	Vegetation & Obstructions				
View of the upstream side of the structure.					
rduffey_20080917_29.jpg					

Levee Mile Report Line	1				
Start Levee Mile	0.00				
End Levee Mile	0.00				
Location					
Category	Structures				
Item	Vegetation & Obstructions				
Downstream at discharge end of the structure from the right bank.					
rduffey_20080917_30.jpg					





Page 3 of 3

Flood Control Project Maintenance

Unit Cover Sheet

2009 Structure Inspection Results

Structure	
Lindo Channel Control Structure	

Structure Rating	Α
Date of Inspection	8/12/2009
DWR Inspector	Bob Duffey
Accompanied By	

Levee Inspection Report By Mile - Structure 2009

Butte County Public Works

Structure	Structure Length	Inspection Start/End	Inspector
Lindo Channel Control Structure			Bob Duffey

LMR	Levee	Mile	Catagory	Itom	Rating ** Location **	Action/Comment	GPS Latitud	de/Longitude	Photo
Z _O	Start	End	Category	Item	ing	Action/Comment	Start	End	o No.
1	0.00	0.00	Structures	Vegetation & Obstructions	Α		0		Y 1
2	0.00	0.00	Structures	Shoaling / Sedimentation	Α		0		_
3	0.00	0.00	Structures	Erosion / Bank Caving	Α		0		U
4	0.00	0.00	Structures	Revetments	Α		0		•
5	0.00	0.00	Structures	Encroachments	Α		0		•
6	0.00	0.00	Structures	Culverts: Inlets / Outlets	А		0		•
7	0.00	0.00	Structures	Culverts: Breaks / Holes / Cracks	А		0		,
8	0.00	0.00	Structures	Metal Pipes	N		0		U
9	0.00	0.00	Structures	Trash Racks	N		0		·
10	0.00	0.00	Structures	Flap Gates	N		0		
11	0.00	0.00	Structures	Sluice/Slide Gates	А		0		
12	0.00	0.00	Structures	Electric Gate Operators	N		0		12
13	0.00	0.00	Structures	Manual Gate Operators	Α		0		10
14	0.00	0.00	Structures	Concrete Surfaces	А		0		
15	0.00	0.00	Structures	Concrete Tilting / Settlement	М		0		10
16	0.00	0.00	Structures	Concrete Foundations	Α		0		10
17	0.00	0.00	Structures	Security Fencing	А		0		17

* Location LS: Land Side WS: Water Side CR: Crown ** Rating

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

Levee Inspection Report By Mile - Structure 2009

Structure		Inspection Start/End	Inspector
Lindo Channel Control Structure			Bob Duffey

LMR	Levee	Mile	Aile Category Item	Rating Action/Comment	GPS Latitude/Longitude			Issue No.		
No.	Start	End	Category	Item	ing tion	Action/Comment	Start	End	oto	No.
18	0.00	0.00	Structures	Closure Structures	Α		0	0		18
19	0.00	0.00	Structures	Trash Rakes	N		0	0		19
20	0.00	0.00	Structures	Other Metallic Items	N		0	0		20
21	0.00	0.00	Structures	Monolith Joints	А		0	0	:	21
22	0.00	0.00	Structures	Safety	N		0	0		22

Levee Inspection Report By Mile - Structure 2009

Structure		Inspection Start/End	Inspector
Lindo Channel Control Structure			Bob Duffey

Levee Mile Report Line	1					
· · · · · · · · · · · · · · · · · · ·						
Start Levee Mile	0.00					
End Levee Mile	0.00					
Location						
Category	Structures					
Item Vegetation & Obstructions						
View of the upstream side of structure.						
rduffey_20080917_27.jpg						

Levee Mile Report Line	1				
Start Levee Mile	0.00				
End Levee Mile	0.00				
Location					
Category	Structures				
Item	Vegetation & Obstructions				
View of the downstream side of structure.					
rduffey_20080917_28.jpg					





Flood Control Project Maintenance

Unit Cover Sheet

2009 Structure Inspection Results

Structure	
Lindo Channel Diversion Weir	

Structure Rating	Α
Date of Inspection	8/12/2009
DWR Inspector	Bob Duffey
Accompanied By	

Levee Inspection Report By Mile - Structure 2009

Butte County Public Works

Structure		Inspection Start/End	Inspector
Lindo Channel Diversion Weir			Bob Duffey

LMR	Levee	Mile	Catagani	Itom	Rating ** Location	Action/Comment	GPS Latitu	de/Longitud	le P	Issue No.
No.	Start	End	Category	Item	ing	Action/Comment	Start	End	ŏ	No.
1	0.00	0.00	Structures	Vegetation & Obstructions	Α			0	° Y	1
2	0.00	0.00	Structures	Shoaling / Sedimentation	Α			0	0	2
3	0.00	0.00	Structures	Erosion / Bank Caving	А			0	0	3
4	0.00	0.00	Structures	Revetments	Α			0	0	4
5	0.00	0.00	Structures	Encroachments	М			0	0	5
6	0.00	0.00	Structures	Culverts: Inlets / Outlets	N			0	0	6
7	0.00	0.00	Structures	Culverts: Breaks / Holes / Cracks	N			0	0	7
8	0.00	0.00	Structures	Metal Pipes	N			0	0	8
9	0.00	0.00	Structures	Trash Racks	N			0	0	9
10	0.00	0.00	Structures	Flap Gates	N			0	0	10
11	0.00	0.00	Structures	Sluice/Slide Gates	N			0	0	11
12	0.00	0.00	Structures	Electric Gate Operators	N			0	0	12
13	0.00	0.00	Structures	Manual Gate Operators	N			0	0	13
14	0.00	0.00	Structures	Concrete Surfaces	А			0	0	14
15	0.00	0.00	Structures	Concrete Tilting / Settlement	Α			0	0	15
16	0.00	0.00	Structures	Concrete Foundations	Α			0	0	16
17	0.00	0.00	Structures	Security Fencing	Α			0	0	17
										—

* Location LS: Land Side WS: Water Side CR: Crown ** Rating

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

Levee Inspection Report By Mile - Structure 2009

Structure	Structure Length	Inspection Start/End	Inspector
Lindo Channel Diversion Weir			Bob Duffey

LMR	Levee	Mile	Catagony	Itom	Rating ** Location	Action/Comment	GPS Latitud	e/Longitude	Issue No.
No.	Start	End	Category	Item	ing tion	Action/Comment	Start	End	ot No.
18	0.00	0.00	Structures	Closure Structures	N		0	0	18
19	0.00	0.00	Structures	Trash Rakes	N		0	0	19
20	0.00	0.00	Structures	Other Metallic Items	N		0	0	20
21	0.00	0.00	Structures	Monolith Joints	А		0	0	21
22	0.00	0.00	Structures	Safety	N		0	0	22

Levee Inspection Report By Mile - Structure 2009

Structure	Structure Length	Inspection Start/End	Inspector
Lindo Channel Diversion Weir			Bob Duffey

Levee Mile Report Line	1		
Start Levee Mile	0.00		
End Levee Mile	0.00		
Location			
Category	Structures		
Item	Vegetation & Obstructions		
Upstream side of the structure from the left bank.			
rduffey_20080917_25.jpg			

Levee Mile Report Line	1				
Start Levee Mile	0.00				
End Levee Mile	0.00				
Location					
Category	Structures				
Item Vegetation & Obstructions					
The velocity dissipaters on the downstream side of structure from the left bank.					



